This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



PROVIDING FIBER BUNDLE A SZOZ Cuthing FBERBUNDLE INTO Sheets OF FIBER BUNDLE SEMONTS MODIFING ENDS OF FIBER -5206 BUNDLE SEEMONTS Exposing FIBER BUNDLE ENDS TO A ROPETUE LIQUID TOFORM COMME THE TIPS WITH A CONDUCTIVE MATERIAL F16. 2 DEPOSITING A DIELEZAMIC/25212 LAVER FORMING A GATE ELEZARADE IN 5214 tr 5216 Removing Portions OF THE DIELECTRIC LAYER TO EXPOSE THE COMED TIPS







F16.7

